

## Industrial Troubleshooting Kit

### Features:

- Assembled to provide all the electrical testing needs for installation and repair of electrical systems, HVAC equipment and large appliances
- EX430 True RMS multimeter includes 11 functions (AC/DC Voltage and Current, Resistance, Capacitance, Frequency, Temperature, Duty Cycle, Diode, and Continuity)
- 42510 Mini IR Thermometer offers non-contact temperature measurements on surfaces difficult or unsafe to reach (-58 to 1000°F/-50 to 538°C)
- MA200 400A AC Clamp Meter includes 6 functions (AC Current, AC/DC Voltage, Resistance, Diode, and Continuity)
- 40130 Non-contact AC Voltage Detector measures voltages from 100V to 600V
- Supplied in an attractive storage case that provides protection and organization for the meters whenever they are needed
- Dimensions: 9.5x6.8x2.8" (241x173x71mm)
- Includes EX430 True RMS autoranging digital multimeter, MA200 400A clamp meter, 42510 Mini InfraRed Thermometer, 40130 Non-Contact voltage detector, set of CAT III-1000V test leads, Type K thermocouple bead probe, Type K to Banana Input Adaptor, multimeter hanging strap, and batteries



CE

### Ordering Information:

TK430-IR.....Industrial Troubleshooting Kit

**"Make mine an Extech!"™**